



MPX Firmware/Software Updates

Software version 1.1.13

May 31, 2012

Release Scope:

General availability

New features and improvements:

1. Supports VoIP G.723 and G.729 codecs.

Known issues or limitations:

- a. Nothing major to report.

Software version 1.1.10

June 2, 2011

Release Scope:

General availability

New features and improvements:

1. Added RFC2544 asymmetric measurement support. The MPX will act as a responder to another controller test set: MX100/120+, MX300/TX300, CX350/CX380.
2. Added EtherType configuration
3. Added VLAN configuration on the management port
4. Changes the RFC2544 Latency measurement to average on all test frames.

Known issues or limitations:

- a. Nothing major to report.

Software version 1.1.8

May 18, 2010

Release Scope:

General availability

New features and improvements:

1. Added VLAN ID configuration for the test port in the "Test Port IP" menu

Known issues or limitations:

- a. Nothing major to report

Software version 1.1.7

January 21, 2010

Release Scope:

General availability

New features and improvements:

1. Fixed a loopback control bug where the MPX could not be looped up by the MX300.
2. Added the ability to remember the last port setup configured before shut down.

Known issues or limitations:

- a. Nothing major to report



MPX100 Ethernet Test Probe

Software Release Notes

© 2012 VeEX Inc. All rights reserved.

VeEX, VePAL, ReVeal, V-SAM, V-SCAN, Multi-BERT, and the V logos are trademarks or registered trademarks of VeEX Incorporated, or one of its affiliates. All other trademarks or registered trademarks are the property of their respective owners.

Some features listed in this document require software options that may require paid activation or license, and may or may not be available in all products. VeEX Inc., reserves the right to change, without notice, product offerings or specifications.